

## 固件升级及 导出日志诊断报告

2026/06

Byteon





## 从矿机界面操作



### 【 固件升级 】 固件更新





## 【<mark>固件升级</mark>】上传update文件

		哈希率	温度	功率	错误	性能 ス		
1 仪表板		105.91 当前: 105.7 / Theor: 123.4	53 <sup>-</sup> -71 <sup>-</sup> 电路板: 38 <sup>-</sup> -56 <sup>-</sup>	3069 估计数据		3670 watt ~ 120 TH Disabled		
		IH/s IA 茶家	固件更新	Antminer S19J	ro ami v1.2.6-rc5   🏨 💙	32(4): 34.6 J/TH PSU: APW1212158		
1200		180 120						
↓ 系统						25% 0%		
		范围:				1/181 12/183 24/183		
	<b>新方地</b> 71 45.204.13.203:330 :stg88888.8.148		将文件拖放到此处或单击以上传			风扇 7 风扇 1 风扇 2 5820 RPM 88 6000 RPM 88		
		45.204.13.203:330 zfg888888.8x148 45.204.13.203:330 zfg888888.8x148	3件文件:			风崩 3 5880 RPM 88 560 RPM 88		
		DevFee: Online		◇ 刷新矿机		根式: 自动 风扇转速: 97%		
		电路板 1 7 32.56 TH/s 0.0 HR (00.86%) 错 635.00 Mhz 13 频率 电印	00 H/s 53 - 70 °C 周 温度 20 V 1223 W E 初時	电路板 2 刁 35.85 TH/s 0.00 H/s <sup>HR (87.46%)</sup> 错误 635.00 Mhz 13.20 V 频率 电压	53 - 70 °C 温度 1223 W 功耗	<ul> <li>电路板3 ス</li> <li>37.28 TH/s</li> <li>0.00 H/s</li> <li>53 - 71 *C</li> <li>Hit (03 19%)</li> <li>皆頃</li> <li>高度</li> <li>655.00 Mhz</li> <li>13.20 V</li> <li>1223 W</li> <li>病率</li> <li>电压</li> <li>20H</li> </ul>		
			19 5		8 6	112 10 4		
		47 JEW 44		Y JEW T				



## **固件升级** 上传完成后,刷新矿机,完成固件更新







## 从Toolkit界面操作



## 【固件升级】<sub>点击"命令"</sub>







## 【固件升级】点击"更新固件"



	<b>t</b> ☰ 视图 ~
Z Antminer S19J Pro     105.74 TH/s     3669 W     53-71° C     5850 6000 5820 4590     3670 / 3670 / /     ● 1.2.6+rc5     1:58     ● ひゃ     の      の     の     の      の	● 章 范 插:45.204 aml nand PIC 合 《 自动超频 :
21 思想得1个 🗙	
操作         品 更改矿池         三 重置超频配置         ② 保存诊断报告         ③ 查找矿机       採用 屈用         四件         ③ 安装四件         ③ 更新雷件       ●         ● 母紙 ● 母紙 ● 母紙 ● 母紙 ● 番         ● 日紙       ●         ● 日紙       ●	
@2025 HashCore. 保留所有权利	★###考明用



## **固件升级)**选择文件夹—>更新选项—>矿机型号—>更新固件







## 

(☆) > jpro-02 test 2 ~ ↓ 1 合和、↓ 1 合和、↓ 1 合和、↓ 1 合素報、↓ 1 合素報、↓ 1	①     105.91 TH/s     读     3.67 kW     ·	
	C 5850 6000 5820 4590 3670/3670// • 1.2.6-rc5 1:58 東小和時代 自己 起時記書/目前/商小和大 点 医件 の以行対詞 の第力	谷池1:45.204 aml nand PIC 6 《 自动超频 根 好1: zfg888 aml nand PIC 6 《 自动超频
	② 更新固件 ×	
	更新固件 1 台设备	
	✓ 是	
	× 取消	
	已法岸1个 X 29 隅高 【】 重新扫描 4 合令 >	







## 从矿机界面操作









# **三、导出诊断报告**

## 从矿机界面操作



## 法一: 【诊断报告】





## 一: (诊断报告) 填写矿机问题后,创建报告并保存





## 法二: 【技术支持】





## **法二: 【技术支持】**—> 诊断报告

	← 仪表板							
		哈希率 97.07	温度 52°-70°	功率 3669	错误 0%	性能 □ 预设 3670 watt ~ 120 TH		
山 仪表板		当前: 101.8 / Theor: 113.7 TH/s	电路数: 37*-55*			效率: 37.8 J/TH	PSU: APW121215a	
		哈希率 기	技术支持		×			
<u>《</u> 挖矿			A	S	1		75% 50%	
\$↓} 系统				l	5		25% 0% 00 05:00 07:00 09:00	
		3018: <b>矿池</b> ス 45.204.13.203.3301 より688388.8.148 45.204.13.203.3301 より688388.8.148	诊断报告	Rifetti	四時推出	风扇 7 风雨 1	17/09 12/09 24/099 UR 2 000 RPM 88 UR 4	
	日志		Telegram 頻道 主页					
2. 技术支持 7	Kat     Gits/l     Badgig     Support       1     3.5000000000000000000000000000000000000							
								~
· 個件更新 7	日志					× 8 0 B	动调谐中 Antminer S19J Pro aml	



## **法二: 【技术支持】**诊断报告填写矿机问题后, 创建报告并保存

